



## **CERTIFICATE OF AUTHENTICITY**

**THIS IS TO CERTIFY THAT THE FOLLOWING ELECTRONIC RECORDS ARE TRUE AND ACCURATE REPRODUCTIONS OF THE ORIGINAL RECORDS OF JAMES CITY COUNTY GENERAL SERVICES DEPARTMENT- STORMWATER DIVISION; WERE SCANNED IN THE REGULAR COURSE OF BUSINESS PURSUANT TO GUIDELINES ESTABLISHED BY THE LIBRARY OF VIRGINIA AND ARCHIVES; AND HAVE BEEN VERIFIED IN THE CUSTODY OF THE INDIVIDUAL LISTED BELOW.**

**BMP NUMBER: CC-013**

**DATE VERIFIED: March 22, 2012**

**QUALITY ASSURANCE TECHNICIAN:**

**Leah Hardenbergh**

*Leah Hardenbergh*

**LOCATION: WILLIAMSBURG, VIRGINIA**



## Stormwater Division

### MEMORANDUM

**DATE:** March 10, 2010  
**TO:** Michael J. Gillis, Virginia Correctional Enterprises Document Management Services  
**FROM:** Jo Anna Ripley, Stormwater  
**PO:** 270712  
**RE:** Files Approved for Scanning

---

**General File ID or BMP ID:** CC013

**PIN:** 4840100011

**Subdivision, Tract, Business or Owner**

**Name (if known):**

Vineyards at Jockeys Neck  
Common Area Landscape and Hardscape Easements  
and Open Space  
2630 Lake Powell Road

**Property Description:**

**Site Address:**

*(For internal use only)*

**Box** 10

**Drawer:** 6

**Agreements:** (in file as of scan date)

**N**

**Book or Doc#:**

**Page:**


Comments

CC013


**Contents for Stormwater Management Facilities As-built Files**

Each file is to contain:

1. As-built plan
2. Completed construction certification
- ③ Construction Plan
- ④ Design Calculations
- ⑤ Watershed Map
6. Maintenance Agreement
7. Correspondence with owners
8. Inspection Records
9. Enforcement Actions

[illegible]


**AES**, a professional corporation  
1761 Jamestown Road  
Williamsburg, Virginia 23185  
804-253-0040  
Engineering, Planning, Surveying



**DAM AND LAKE NO.1**  
**PLAN**  
**JOCKEY'S NECK**  
OWNER : DAVID M. MURRAY  
CITY COUNTY

Designed SOW	Drawn GSB/RMS
Scale 1"=50'	Date JULY, 1986
Project No. 6518	
Drawing No. 1 of 2	


CC 0.13 JOACHIM LAKE (DAM #1)











**DAM AND LAKE NO.2  
JOCKEY'S NECK**  
OWNER/DAVID M. MURRAY

**JAMES CITY COUNTY** **VIRGINIA**



- Property is some A-2 and is currently under cultivation.
- All disturbed areas shall be permanently seeded within 30 days after achieving final grade. Should an area be disturbed initially with the intent of not being brought to final grade in a reasonable amount of time, that area shall be temporarily seeded within 15 days of the initial disturbance.
- Point clearing area: All stumps below elevation 16' shall remain (except under dam) to provide habitat for fish and wildlife.
- Stumps to be removed between elevation 16' and 22' along the entire perimeter of the lake. Lake perimeter to be contoured where practical.
- All joints in concrete pipe and D.I. structure to be well grouted for water tightness.
- Strip and stockpile topsoil at location approved by the Owner or Engineer.
- Area borrow to be located in closed proximity to dam (within 1000 feet). Borrow areas are to be graded, topsoiled and stabilized after completion of filling/borrowing activities.

DAM STATISTICS

CREST OF DAM = 40'

EMERGENCY SPILLWAY ELEV. = 26.5'

100 YEAR STORM ELEV. = 23.5'

10 YEAR STORM ELEV. = 23.25'

NORMAL POOL AND PRINCIPLE SPILLWAY CREST ELEV. = 22.5'

DAM DESIGNED TO DETAIN	2YR. STORM	10YR. STORM	100YR. STORM
POND VOL. (FT. <sup>3</sup> )	4325000	4540000	4750000
SPILLWAY RELEASE RATES (CFS)	69	13.1	19.3

AREA OF POND @ NORMAL POOL = 11.1 AC.

DRAINAGE AREA SERVED = 101.1 AC. PLUS DAM #1 OUTFLOW

DRAINAGE AREA TO POND SURFACE RATIO = 10:1

HEIGHT OF DAM @ CREST = (14.5')

LENGTH OF DAM = 100'

MAX. WIDTH OF DAM = 170'

MAX. DEPTH OF NORMAL POOL = 14.5'

AVG. DEPTH @ MID-LAKE = 11'

[illegible]

Designed SOW	Drawn SOW
Scale NOTED	Date JULY 87
Project No. 658-2	
Drawing No. 1 OF 1	



# Detention Pond Design for Jockey's Neck

(Use "Detention Pond Design For Small Basins")

by Steve Wight  
6/5/86

## Pre-development

Drainage Area -  $A = 108.8 \text{ ac}$  (As per J.C.C. Topo)

Composite "C" value - 40% Woodlands  $C = 0.2$   
60% Cultivated rows w/crop  $C = 0.25$

Use  $C = 0.23$

$CA = 25.02$

Time of Concentration -  $t_c = 44 \text{ min}$

$L = 3520$

$\Delta \text{Elev.} = 57.4'$   $S = 0.007$   
(As per Fig. 15.11, Crisp "Design  
Book for Civil Eng. E.E. Co.

Intensity -  $I = \left( \frac{a}{b + t_c} \right)$  where  $a_2 = 130.3$   $b_2 = 18.5$   
 $a_{10} = 189.2$   $b_{10} = 22.1$   
 $I_2 = 2.1 \text{ in/hr}$   $I_{10} = 2.9 \text{ in/hr}$   $I_{100} = 5.0 \text{ in/hr}$

$Q_2 = CI_2A = 25.02(2.1) = 52.6 \text{ cfs}$

$Q_{10} = CI_{10}A = 25.02(2.9) = 72.6 \text{ cfs}$

$Q_{100} = CI_{100}A = 25.02(5.0) = 125.10 \text{ cfs}$

## Post-development

45% Paved  $A = 57.6 \text{ ac}$  @  $C = 0.45$

$CA = 25.72$

55% Unimproved  $A = 70.4 \text{ ac}$  @  $C = 0.23$

$CA = 16.19$

$\Sigma A = 128 \text{ ac}$

$\Sigma CA = 41.91$

Use  $C = 0.33$

$L = 2900 \text{ L.F.}$      $\Delta \text{Elev.} = 57.4'$      $S = 1.98\%$

$t_c = 16 \text{ min.}$

$I_2 = 3.8 \text{ in./hr.}$  ,  $Q_2 = 160.5 \text{ cfs}$  ... a 304% increase  
 $I_{10} = 5.0 \text{ in./hr.}$  ,  $Q_{10} = 211.2 \text{ cfs}$  ... a 289%  
 $I_{100} = 8.1 \text{ in./hr.}$  ,  $Q_{100} = 342.1 \text{ cfs}$  ... a 274%

- Critical Storm Duration for Zyr. Post-Development:

$T_c = \sqrt{\frac{2CAa(b - t_c/4)}{g_0}} - b$     given:  $C = 0.33$   
 $A = 128$   
 $t_c = 16$   
 $a = 130.3$   
 $b = 18.5$   
 $g_0 = 52.6$   
 $T_c = \sqrt{\frac{2(0.33)(128)(130.3(18.5 - 16/4))}{52.6}} - 18.5$   
 $T_c = 36.6 \text{ min.}$

$t_c = 16 \text{ min.}$

- Peak Inflow

$Q_0 = CA \left( \frac{a}{b + T_c} \right) = 0.33 \left( \frac{130.3}{18.5 + 36.6} \right) 128 = 99.9 \text{ cfs}$

- Reg'd Storage for Critical Zyr. Storm


$V = \left[ Q_0 T_c + \frac{Q_0 t_c}{4} - \frac{g_0 T_c}{2} - \frac{3g_0 t_c}{4} \right] 60$   
 $= \left[ 99.9(36.6) + \frac{99.9(16)}{4} - \frac{52.6(36.6)}{2} - \frac{3(52.6)(16)}{4} \right] 60$

$V = 147,730 \text{ ft}^3$     Say 150,000 ft<sup>3</sup>

- Reg'd Sediment Storage Val.

$V = 67 \frac{\text{cu ft}}{\text{sq ft}} (128) = 231,552 \text{ cu ft}$

check:



Area  
 I  $99.9(16)^{1/2} = 799.2$   
 II  $99.9(20.6) = 2057.9$   
 III  $99.9(24)^{1/2} = 1198.8$   
 4055.9

Unshaded Area  
 $- 52.6(60.6)^{1/2} = -1593.78$

$2462.12(60) = 147727.2$




## Basin Characteristics

Elev.	Area (ft <sup>2</sup> )	Incremental Vol. (ft <sup>3</sup> )	Σ Vol. (ft <sup>3</sup> )
24.5	0	0	0
25	200	100	100
26	10875	11075	11175
28	18525	29400	40575
30	37850	56375	96950
32	57575	95425	192375
34	79575	137150	329525
36	100400	179975	509500
38	124225	224625	734125
40	149125	273350	1007475
42	186250	335375	1342850
44	222375	408625	1751475

— See Basin Characteristics Graph —

# Basin Characteristics Graph





## Storage Elevations

Sediment Storage of 231552 ft<sup>3</sup> → Elev. 24.5 to 32.2  
 Permanent Retention → Elev. 32.8 to 37.0  
 Need 150000 ft<sup>3</sup> of detention → Elev. 37.0 to 38.5

Depth 3.2  
 Vol. = 675000  
 Vol. = 735000

## Outlet Structure:

Use Precast Structure w/ Rectangular weir

$$Q = 3.33(L - 0.24)H^{3/2}$$

where:  $Q = 40.03 \text{ cfs}$   
 $H = 1.5 \text{ ft}$

$$L = \left[ \frac{Q}{3.33 H^{3/2}} + 0.24 \right] = \left[ \frac{40.03}{3.33 (1.5)^{3/2}} + 0.24 \right]$$


$$L = 6.84 \text{ ft}$$

Size Structure's Inside Dia. by checking for min. 3H and contraction req'm't.

Trial & Error Procedure

Try I, Dia = 5.5'  
 Perimeter =  $2\pi r = 17.27'$   
 $2(3H) = 9'$  req'd  
 $\therefore 17.27 - 6.84 = 10.43'$  Good

Try I, Dia = 5.0'  
 Perimeter = 15.71'  
 $\therefore 15.71 - 6.84 = 8.87'$  Close Enough



Assume orifice flow condition occurs after water level reaches elev. 38.5' (1.5' above surge event weir). To raise flood use trial & error.

Water Surf Elev. (ft)    Outflow (cfs)

37  
38  
39  
40  
41  
42

0  
21.8  
69.9  
85.7  
98.8  
110.5

Weir  $Q = 3.33(L - 0.24)H^{3/2}$   
 $L = 6.84'$      $h = 1'$   
 Orifice  $Q = 0.6A\sqrt{2gh}$      $h = 2'$      $A = 0.25\pi$   
 $h = 3'$   
 $h = 4'$   
 $h = 5'$

Determine Hydraulic Performance of structure under 10 yr. & 100 yr. peak discharge storm conditions.

$Q_{10} = 124.2 \text{ cfs}$      $Q_{100} = 219.0 \text{ cfs}$      $t_c = 12 \text{ min}$

10 yr Storm  $Q_{in} = 211.2 \text{ cfs}$

(4)

Try Elev. 39'  $g_o = 69.9 \text{ cfs}$

$$\Delta \text{Storage} = 870000 - 625000 = 245000 \text{ ft}^3$$

$$V_o = \left[ Q_o T + \frac{Q_o t_c}{4} - \frac{g_o T}{2} - \frac{3g_o t_c}{4} \right] 60$$

Assume critical storm duration  $T$  for a 10 yr storm equals  $t_c \therefore T = t_c = 16 \text{ min.}$

$$\begin{aligned} \text{Then, } V_o &= 60 t_c (Q_o + \frac{1}{4} Q_o - \frac{1}{2} g_o - \frac{3}{4} g_o) \\ &= 60 t_c (\frac{5}{4} Q_o - \frac{5}{4} g_o) \\ &= 75 t_c (Q_o - g_o) \end{aligned}$$

$$V_o = 75(16)(211.2 - 69.9) = 169560 \text{ ft}^3 \quad \text{Elev. too High}$$

Try Elev. 38.5'  $g_o = \left[ \frac{21.8 + 69.9}{2} \right] = 45.9 \text{ cfs}$

$$\Delta \text{Storage} = 785000 - 625000 = 160000 \text{ ft}^3$$

$$V_o = 75(16)(211.2 - 45.9) = 198360 \text{ ft}^3 \quad \text{Elev. too Low}$$

Therefore say 10 yr storm is at Elev. 38.75'

100 yr Storm  $Q_{in} = 342.1 \text{ cfs}$

Try Elev. 40'  $g_o = 85.7 \text{ cfs}$

$$\Delta \text{Storage} = 1025000 - 625000 = 400000 \text{ ft}^3$$

$$V_o = 75(16)(342.1 - 85.7) = 307680 \text{ ft}^3 \quad \text{Elev. too high}$$

Try Elev. 39.5'  $g_o = \left[ \frac{85.7 + 69.9}{2} \right] = 77.8 \text{ cfs}$

$$\Delta \text{Storage} = 950000 - 625000 = 325000 \text{ ft}^3$$

$$V_o = 75(16)(342.1 - 77.8) = 317160 \quad \text{Close enough!}$$

Therefore 100 yr. storm is at Elev. 39.5'



# Conclusion

Orifice will pass 77.8 cfs at elev. 39.5 while allowing for 100 yr. storm detention and release at a controlled rate minimizing damage to down stream channel. Provide D.E. to at elev. 40' and allow 1.5' freeboard to 20' emergency spillway, elev. 41.5'. Emergency spillway is designed to operate in excess of 100 yr. frequency storm. Allow 2' more to top of dam for freeboard and construction tolerance, elev. 43.5'. The extra height of dam in combination with a 40' width of dam at the crest is to permit future development of a roadway across the dam.

## Outlet Pipe Design

Pipe to pass 77.8 cfs

∴ Use 120' of 36" RCP @ 2.5%

$$Q_{cap} = 95 \text{ cfs}$$

## Anti-Seep Collar Design (Design for Small Dam $\leq 10'$ )

Design collars to increase the seepage path by 15%

$$\text{Length of 36" RCP} = L = 120 \quad 120(0.15) = 18'$$

18' of verticle displacement of seepage path is needed.

H = height of collar

N = # of collars

$$N = \frac{18}{2H}$$


$$\text{Try } H = 1.5' \quad \therefore N = 6$$

$$\text{Try } H = 2' \quad \therefore N = 4.5 \text{ say } 5$$

Therefore use 5 collars w/ H = 2' above pipe o.c. of 16' (2 joints of pipe)

Increase in seepage path:

$$5[2(2)] + 120' = 1.17$$



17% Good

# Buoyancy Calc for Inlet Structure

6

Wt & Vol of 18 ft. structure:

$$\text{Barrel} - \text{Vol.} = (A_{\text{top}} - A_{\text{ext}})h = \left[ \pi \left( \frac{36.75}{12} \right)^2 - \pi \left( \frac{30}{12} \right)^2 \right] 17 = 167.1 \text{ ft}^3$$

$$\text{Top} - \text{Vol} = Ah = \pi \left( \frac{36.75}{12} \right)^2 0.5 = 14.7 \text{ ft}^3$$

$$\text{Base} - \text{Vol.} = Ah = \pi \left( \frac{43.75}{12} \right)^2 0.67 = 28 \text{ ft}^3$$

(extended = 87.5" O.D.)

$$\text{Total Vol.} = 209.8 \text{ ft}^3$$

$$W_{\text{conc}} = 150 \text{ #/ft}^3$$

$$\text{Total Wt} = 209.8 (150 \text{ #/ft}^3)$$

$$\text{Wt}_r = 31470 \text{ #}$$


Wt & Vol. of H<sub>2</sub>O displaced by Air

$$\text{Vol.} = (15 - 3.85) \left[ \pi \left( \frac{30}{12} \right)^2 \right]$$

$$\text{Vol.} = 218.9 \text{ ft}^3$$

$$W_{\text{H}_2\text{O}} = 62.4 \text{ #/ft}^3$$

$$\text{Wt}_w = 218.9 (62.4) = 13659 \text{ #}$$



$\text{Wt}_r > \text{Wt}_w$  Will not float



# Upstream 39" RCP Capacity Calc.

Inv. In

39" RCP  
Inv. Elev. = 37.35'

$$\begin{array}{r} 37.35 \\ + 3.25 \\ \hline 40.60' = \text{Top RCP Elev.} \end{array}$$

Inv. Out

42" RCP  
Inv. Elev. = 36.57'


$$\begin{array}{r} 36.57 \\ + 3.50 \\ \hline 40.07' = \text{Top RCP Elev.} \end{array}$$


Length 65'

$$\text{Slope} = S = \frac{40.60 - 40.07}{65} = \frac{0.53}{65} = 0.008 \text{ ft/ft}$$

Normal Pool Elev. = 39'  
Zyr. storm detention = 41'

@ 41' the culverts will be under water.





SECTION A-A

ELEVATION

PRECAST RISER W/ ORIFICE

N.T.S.



Jockey's Neck  
Dam #II

7/21/87  
SPW.

Pre-development

Drainage Area = 4752000 S.F. = 109.1 Ac.

Composite "C" Value

	Area	C	CA
Woodlands	43.2 Ac.	0.2	8.64
Cultivated Paddy/crop	65.9 Ac.	0.25	16.48
	109.1		25.12
	$C = 25.12 / 109.1 = 0.23$		

$L = 3060 \text{ L.F.}$        $\Delta \text{Elev.} = 61 - 4 = 57'$   
 $S = 1.86\%$

$t_c = 36 \text{ min}$  (Fig. 1.5.12.)

$I_2 = 2.2 \text{ in/hr.}$  ,  $Q_2 = 55.2 \text{ cfs}$

$I_{10} = 3.6 \text{ in/hr.}$  ,  $Q_{10} = 90.3 \text{ cfs}$

$I_{100} = 5.5 \text{ in/hr.}$  ,  $Q_{100} = 138.0 \text{ cfs}$

Post-development

Assume surrounding environs developed to:

90% Residential = 98.2 Ac. @  $C = 0.40$   
 10% Woodlands = 10.9 Ac. @  $C = 0.23$

$CA = 39.3$   
 $CA = 2.5$

$\Sigma A = 109.1 \text{ Ac}$

$\Sigma CA = 41.8$

$C = 0.38$

$t_c = 18 \text{ min.}$  (Fig. 1.5.12.)

$I = \frac{a}{b + t_c}$

$a_2 = 130.3$        $a_{10} = 189.2$   
 $b_2 = 18.5$        $b_{10} = 22.1$

$I_2 = 3.57 \text{ in/hr.}$  ,  $Q_2 = 148.0 \text{ cfs}$  — a 268% increase  
 $I_{10} = 4.72 \text{ in/hr.}$  ,  $Q_{10} = 195.7 \text{ cfs}$  — a 216% increase  
 $I_{100} = 7.90 \text{ in/hr.}$  ,  $Q_{100} = 327.5 \text{ cfs}$  — a 237% increase

- Critical Storm Duration For 2yr. Peak - de

$$T_c = \sqrt{\frac{2CAa(b - t_c/4)}{g_0}} - b$$

$$T_c = \sqrt{\frac{2(0.38)(109.1)(130.3)(18.5 - 18/4)}{55.2}} - 18.5$$

$$T_c = 24.6 \text{ min.}, t_c = 18 \text{ min.}$$

given:  $C = 0.38$

$A = 109.1 \text{ Ac}$


$t_c = 18 \text{ min}$

$a = 130.3$

$b = 18.5$

$g_0 = 55.2 \text{ cfs (allowable peak out)}$

- Dam #1 Inflow & Outflow Hydrograph



- Peak Inflow

$$Q_0 = CA \left( \frac{a}{b + T_c} \right) = 0.38(109.1) \left( \frac{130.3}{18.5 + 24.6} \right) = 125.3 \text{ cfs}$$

Dam #1 Outflow = 52.6 cfs

$Q_0$ , Peak Inflow = 177.9 cfs

- Req'd Storage for Critical 2yr. Storm

$$V = \left[ Q_0 T_c + \frac{Q_0 t_c}{4} - \frac{g_0 T_c}{2} - \frac{3g_0 t_c}{4} \right] 60$$


$$= \left[ 177.9(24.6) + \frac{177.9(18)}{4} - \frac{55.2(24.6)}{2} - \frac{3(55.2)(18)}{4} \right] 60$$

$$= 225164 \text{ ft}^3 \rightarrow \text{say } 225000 \text{ ft}^3$$

- Req'd Sediment Storage Vol.


$$V = 67(109.1)27 = 197362 \text{ ft}^3 \rightarrow \text{say } 200000 \text{ ft}^3$$

Elev. (ft.)	Area (ft <sup>2</sup> )	Avg. Area (ft <sup>2</sup> )	Depth (ft.)	Incremental Vol. (ft <sup>3</sup> )	Σ Vol. (ft <sup>3</sup> )
4	0				
		6000	1	6000	
5	12000				6000
		72000	5	360000	
10	132000				366000
		198000	5	990000	
15	264000				1356000
		328000	5	1640000	
20	392000				2996000
		484000	5	2420000	
25	576000				5416000





Check:



Area

$$\begin{array}{l} \text{I} \quad 177.9(18) \frac{1}{2} = 1601 \\ \text{II} \quad 177.9(6.6) = 1174 \\ \text{III} \quad 177.9(27) \frac{1}{2} = 2402 \\ \hline 5127 \end{array}$$

Unshaded Area

$$55.2(51.6) \frac{1}{2} = 1424$$

$$3753$$

$$V = 3753(60) = 225170 \text{ ft}^3$$

check:

### - Storage Elevations

	Elev.	Vol. (ft <sup>3</sup> )
Sediment Storage of 200000 ft <sup>3</sup>	4' to 8.3'	200000
Permanent Retention	8.3 to 22.5'	4100000
Required 225000 ft <sup>3</sup> detention		

### - Outlet Structure

Use Precast Structure w/ Rectangular Weir

(Weir Egn)  $Q = 3.33(L - 0.2H)H^{3/2}$

where  $L = 6.0 \text{ ft}$   
 $H = 1.5 \text{ ft}$

$$Q = 3.33 [6 - 0.2(1.5)] 1.5^{3/2} = 34.9 \text{ cfs} < 55.2 \text{ cfs} \quad \text{Good}$$

Assume orifice flow condition occurs after water level reaches elev. 24 ft (1.5 ft above weir inv.)

(Orifice Egn)  $Q = 0.6A\sqrt{2gh}$

Water Surface Elev. (ft.)      Outflow (cfs)

22.5	0
23.0	6.9
23.5	19.3
24.0	34.9
24.5	61.3

where  $A = 9 \text{ ft}^2$   
 Equation

Weir


$$L = 6, h = 0.5$$

$$L = 6, h = 1$$

$$L = 6, h = 1.5$$

Orifice  $A = 9, h = 2$

$$h = 2.5$$



- Determine Hydraulic Performance of Structure under 10 yr & 100 yr peak discharge storm conditions

$$Q_{10} = 195.7 \text{ cfs} \quad t_c = 18 \text{ min.}$$

$$Q_{100} = 327.5 \text{ cfs}$$

10 Yr. Storm  $Q_{in} = 195.7 \text{ cfs}$

Try Elev. = 23.5  $g_o = 19.3$

$$A_{\text{storage}} = 4575000 - 4100000 = 475000 \text{ ft}^3$$

$$V_o = 75 t_c (Q_{in} - g_o) = 75(18)(195.7 - 19.3) = 232140 \text{ ft}^3 \quad \text{Elev. too high}$$

Try Elev. 23.0  $g_o = 6.9$

23.0 is the 2 yr. storm elev., therefore the 10 yr storm event is between 23.0 & 23.5 say  $\rightarrow$  Elev. = 23.25'

100 yr. Storm  $Q_{in} = 327.5 \text{ cfs}$

Try Elev. = 23.5  $g_o = 19.3$

$$A_{\text{storage}} = 4750000 \text{ ft}^3$$

$$V_o = 75(18)(327.5 - 19.3) = 416070 \text{ ft}^3 \quad \text{close enough}$$

Elev. = 23.5 ft

Total Discharge Under 100 yr. Storm Conditions

$$Q_o = 19.3 \text{ cfs} \rightarrow \text{Use } g_z = 55.2 \text{ cfs (allowable peak flow)}$$

Use @ 30" KCP @ 2.3%  $Q_{req} = 53 \text{ cfs}$

### Anti-Seep Collar Design

Design Collars to increase the seepage path by 15%

Length of 30" RCP = 128'  $128(0.15) = 19.2'$

20' of verticle displacement of seepage path is needed.

$$H = \text{height of collar} \quad N = \frac{20}{2H}$$

$$N = \# \text{ of collars}$$

Try  $H = 2'$ , then  $N = 5$

Use 5 collars w/  $H = 2'$  above pipe, o.c. of 16' (2 joints & 2 collars)

Increase in seepage path:

# Buoyancy Loads For Inlet Structure

Wt. & Vol. of 23.5 ft. Structure:

$$\text{Barrel} - \text{Vol.} = (A_{\text{out}} - A_{\text{in}})h = \left[ \pi \left( \frac{36.75}{12} \right)^2 - \pi \left( \frac{30}{12} \right)^2 \right] 23.5 = 221.2 \text{ ft}^3$$

$$\text{Top} - \text{Vol.} = Ah = \pi \left( \frac{36.75}{12} \right)^2 0.5 = 14.7 \text{ ft}^3$$

$$\text{Base} - \text{Vol.} = Ah = \pi \left( \frac{43.75}{12} \right)^2 0.67 = 28 \text{ ft}^3$$

(extended = 87.5' O.D.)

$$\text{Total Vol.} = 263.9 \text{ ft}^3$$

$$\text{Total Wt.} = 263.9 (150 \text{ lb/ft}^3)$$

$$\text{Wt}_T = 39585.0 \text{ lb}$$

$$W_c = 150 \text{ lb/ft}^3$$


Wt. & Vol. of H<sub>2</sub>O displaced by Air

$$\text{Vol.} = (20.5 - 3.5) \pi \left( \frac{30}{12} \right)^2$$

$$\text{Vol.} = 333.8 \text{ ft}^3$$


$$W_{H_2O} = 62.4 \text{ lb/ft}^3$$

$$\text{Wt}_w = 333.8 \text{ ft}^3 (62.4) = 20828.8 \text{ lb}$$



$$W_{T+} > W_{T_w} \text{ } \circ \text{ Will Not Float}$$







10

Vineyards  
LAKE EMERGENCY overflow

7/1/39

RM

FT



$$55+00 - 26.84 = 28.16$$

55

53.00


52+26.06 to 5.73 34.03  
TOP W  
53+00  
E TOP  
GRATE  
E CONC. TOP  
E SIDE  
GRATE  
TOP W  
55+00  
51+50 R

28.30  
7.76 26.27 TOP W 53+00  
7.43 26.60 (GRATE @ OVERFLOW)  
7.31 26.72 (TOP OF OVERFLOW)  
10.29 23.74 (SIDE GRATE FLOW)  
7.19 26.84 TOP W 55+00  
6.96 27.07 ± 0.03


Subgrade @ 53+00 28.88  
Subgrade @ 55+00 30.13

Projected Length of Pipe @ 53+00 ± 58'  
Projected Length of Pipe @ 55+00 ± 68'

← PROJECTED LENGTH OF PIPE →



$$\begin{array}{r} 29.72 \\ 26.84 \\ \hline 2.88 \end{array}$$



# AES, A PROFESSIONAL CORPORATION

Engineering And Surveying

1761 Jamestown Road, Suite 1  
WILLIAMSBURG, VIRGINIA 23185

## LETTER OF TRANSMITTAL

(804) 253-0040

TO

V.D.O.T.

DATE 8-10-89	JOB NO. 6518
ATTENTION Debbie Lencese	
RE: Jockey's Neck (Williamsburg Winery) Dam I & II	

WE ARE SENDING YOU ☒ Attached ☐ Under separate cover via \_\_\_\_\_ the following items:

- ☐ Shop drawings    ☒ Prints    ☐ Plans    ☐ Samples    ☐ Specifications  
☐ Copy of letter    ☐ Change order    ☒ Calculations

COPIES	DATE	NO.	DESCRIPTION
1	7-86	2 of 2	Dam & Lake No. 1 Site Plan
1	7-87	1 of 1	Dam & Lake No. 2 Site Plan
1	6-5-86	Copy	Dam #1 Calculations
1	7-21-87	Copy	Dam #2 Calculations
1		Copy	Watersheds For Lakes.

THESE ARE TRANSMITTED as checked below:

- ☐ For approval    ☐ Approved as submitted    ☐ Resubmit \_\_\_\_\_ copies for approval  
☒ For your use    ☐ Approved as noted    ☐ Submit \_\_\_\_\_ copies for distribution  
☒ As requested    ☐ Returned for corrections    ☐ Return \_\_\_\_\_ corrected prints  
☐ For review and comment    ☐ \_\_\_\_\_  
☐ FOR BIDS DUE \_\_\_\_\_ 19\_\_\_\_    ☐ PRINTS RETURNED AFTER LOAN TO US


REMARKS

If you have any questions please do not hesitate to call.

Steven C. Wiley



**S-018-02**



**AMENDMENT TO  
THE VINEYARDS AT JOCKEY'S NECK  
PHASE III**

**(JCC CASE NO. S-030-00, Approved December 22, 2000)**

**JAMES CITY COUNTY, VIRGINIA**

**FEBRUARY 2002**

**SUPPORTING ENGINEERING DOCUMENTS**

**STORM DRAINAGE CALCULATIONS**

**EROSION & SEDIMENT CONTROL NARRATIVE**

Calculated by: LMP Date: 3-24-00 Rev 1/30/02 -MCH

Checked By: \_\_\_\_\_ Date: \_\_\_\_\_

N = 0.013 (BCP)

Project No.: 1880039-000.90

Project Desc: VINEYARDS AT

JOCKEY'S NECK PHASE III


Storm Frequency: 10 YEAR

# STORM DRAINAGE COMPUTATION SHEET

Sheet \_\_\_\_\_ of \_\_\_\_\_ Sheets

LOCATION			RUN-OFF										PIPE - CHANNEL DESIGN										HGL DATA		
LINE I.D.	FROM (UP)	TO (DOWN)	AREA-AC.		RUN-OFF COEFF.	INCREM. CA	ACCUM. CA	FLOW - MIN.			INTENSITY	DISCHARGE C.F.S.	PIPE SIZE	CHANNEL SECTION	SLOPE FT./FT.	CAPACITY FULL(CFS)	VELOCITY FULL(FPS)	DESIGN VEL.(FPS)	CONVEYANCE LENGTH(FT)	INVERT UPSTREAM	INVERT DOWNSTREAM	FRICTION SLOPE (FT./FT.)	VELOCITY (FPS)	COVER ELEV. UPSTREAM	
			INCREMENT	TOTAL				TO INLET/ UPPER RCH	WITHIN REACH	TOTAL TC															
	1	2	0.58	0.58	0.50	0.29	0.29	9.8 12.0	0.1	12.1	5.70	1.65	15"		0.0078	5.70	4.64	3.9	32	29.60	29.35				
	2	4	0.60	1.18	0.50	0.30	0.59		0.6	12.7	5.69	3.36	15"		0.0120	7.08	5.15	5.6	191	29.25	26.95				
	3	4	0.26	0.26	0.50	0.13	0.13	7.2 9.0	0.2	9.2	6.20	0.81	15"		0.0078	5.70	4.64	3.3	32	27.30	27.05				
	4	6	0.26	0.52	0.50	0.13																			
						+ 0.59	0.85	12.7	0.3	13.0	5.60	4.76	15"		0.0110	6.78	5.51	9.9	107	26.95	25.77				
	5	6	0.36	0.36	0.50	0.18	0.18	7.5 8.0	0.2	8.2	6.40	1.15	15"		0.0078	5.70	4.64	3.6	32	26.02	25.77				
	6	9	0.30		0.50	0.15																			
						+ 0.18																			
				2.36		+ 0.85	1.18	13.0			5.55	6.55	15"		0.0380	12.59	10.24	9.73	162	22.45	16.80				
	9	10										6.55	24"		0.0016	9.05	2.88	3.11	32	15.55	15.50				

# Hydraflow Plan View



Project file: Vin3.stm

IDF file: Eastern.IDF

No. Lines: 7

01-30-2002

**AMENDMENT TO THE VINEYARDS AT JOCKEY'S NECK PHASE 3  
HYDRAULIC GRADE LINE CALCULATIONS SUMMARY**

<b>Line No.</b>	<b>To Line</b>	<b>Length</b>	<b>Total Flow</b>	<b>Capac. Full</b>	<b>Pipe Size</b>	<b>Pipe Slope</b>	<b>Inv Elev Up</b>	<b>Inv Elev Dn</b>	<b>HGL Elev Up</b>	<b>HGL Elev Dn</b>	<b>Gr/Rim El</b>	<b>Gr/Rim El</b>	<b>Line ID</b>
		(ft)	(cfs)	(cfs)	(in)	(%)	(ft)	(ft)	(ft)	(ft)	(ft)	(ft)	
1	End	32	6.55	8.94	24	0.16	15.55	15.50	17.52	17.50	23.55	17.80	9-10
2	1	162	6.55	12.58	15	3.80	22.45	16.30	23.47	17.55	30.34	23.55	6-9
3	2	107	4.76	6.78	15	1.10	26.95	25.77	27.82	26.55	31.35	30.34	4-6
4	3	191	3.36	7.09	15	1.20	29.25	26.95	29.98	28.14	33.64	31.35	2-4
5	4	32	1.65	5.71	15	0.78	29.60	29.35	30.21	30.22	33.64	33.64	1-2
6	3	32	0.81	5.71	15	0.78	27.30	27.05	28.14	28.14	31.35	31.35	3-4
7	2	32	1.15	5.71	15	0.78	26.02	25.77	26.45	26.15	30.34	30.34	5-6

LMDG Project No.: 1880039-001.01

Run Date 1/30/02

Project file: Vin3.stm


Return period = 10 Yrs.



# Storm Sewer Profile

Proj. file: Vin3.stm


Elev. (ft)



# Storm Sewer Profile

Proj. file: Vin3.stm

Elev. (ft)



Run Date: 01-30-2002

```

XXXXXXXXXXXX CURB INLET IN A SUMP XXXXXXXXXXXX
P EFFEC. LENGTH (ft) = 9.60                      H (ft) = 0.290
DEPTH OF WATER (ft) = 0.10                      SPREAD (ft) = 4.94

```

```

XXXXXXXXXXXX CURB INLET IN A SUMP XXXXXXXXXXXX
P EFFEC. LENGTH (ft) = 9.60                      H (ft) = 0.290
DEPTH OF WATER (ft) = 0.14                      SPREAD (ft) = 6.80

```

**INLET NUMBER 6****LENGTH 6.0****STATION 19+32**

DRAINAGE AREA = 0.140 ACRES  
DRAINAGE AREA = 0.160 ACRES

C VALUE = .500  
C VALUE = .500

CA = 0.070  
CA = 0.080

FOR THE FIRST SIDE

SUM CA= 0.070 INT= 4.00 CFS= 0.280 CO= 0.010 GUTTER FLOW= 0.290

FOR THE OTHER SIDE

SUM CA= 0.080 INT= 4.00 CFS= 0.320 CO= 0.000 GUTTER FLOW= 0.320

AT THE INLET

SUM CA= 0.150 INT= 4.00 CFS= 0.600 CO= 0.010 GUTTER FLOW= 0.610

GUTTER SLOPE = 0.0010 FT/FT

PAVEMENT CROSS SLOPE = 0.0208 FT/FT

SPREAD AT A SLOPE OF .001 (ft./ft.) AND 0.32 (cfs) IS 5.17 (ft.)

XXXXXXXXXXXX CURB INLET IN A SUMP XXXXXXXXXXXX

P EFFEC. LENGTH (ft) = 9.60

H (ft) = 0.290

DEPTH OF WATER (ft) = 0.09

SPREAD (ft) = 4.38

**INLET NUMBER 6 CHECK STORM****LENGTH 6.0****STATION 19+32**

DRAINAGE AREA = 0.140 ACRES  
DRAINAGE AREA = 0.160 ACRES

C VALUE = .500  
C VALUE = .500

CA = 0.070  
CA = 0.080

FOR THE FIRST SIDE

SUM CA= 0.070 INT= 6.50 CFS= 0.455 CO= 0.010 GUTTER FLOW= 0.465

FOR THE OTHER SIDE

SUM CA= 0.080 INT= 6.50 CFS= 0.520 CO= 0.000 GUTTER FLOW= 0.520

AT THE INLET

SUM CA= 0.150 INT= 6.50 CFS= 0.975 CO= 0.010 GUTTER FLOW= 0.985

GUTTER SLOPE = 0.0010 FT/FT

PAVEMENT CROSS SLOPE = 0.0208 FT/FT

SPREAD AT A SLOPE OF .001 (ft./ft.) AND 0.52 (cfs) IS 6.88 (ft.)

XXXXXXXXXXXX CURB INLET IN A SUMP XXXXXXXXXXXX

P EFFEC. LENGTH (ft) = 9.60


H (ft) = 0.290

DEPTH OF WATER (ft) = 0.13

SPREAD (ft) = 6.03

DRAINAGE RIDGE (TYP)

DRAINAGE RIDGE PER PHASE I



LEGEND



DRAINAGE AREA MAP  
THE VINEYARDS AT JOCKEY'S NECK  
PHASE III

REVISED FEBRUARY 4, 2002

SCALE: 1"=200'



**AMENDMENT TO  
THE VINEYARDS AT JOCKEY'S NECK  
PHASE III  
JAMES CITY COUNTY, VIRGINIA**

**EROSION AND SEDIMENT CONTROL PLAN NARRATIVE  
FEBRUARY 2002**

**PROJECT DESCRIPTION**

Amendment to The Vineyards at Jockey's Neck –Phase III is a proposed 7 lot residential subdivision situated within the overall Vineyards at Jockey's Neck project site. The amendment includes reducing the number of lots from nine to seven, along with shortening Reserve Drive by approximately 180 feet and adjusting utilities as necessary. The Phase III project is located on the west side of Jockey's Neck Trail approximately 2500 feet south of Lake Powell Road. The total project area for Phase III is approximately 23.3 acres of land and is depicted on the site development plans. As shown on the site development plans, approximately 2.2 acres will be cleared for demolition of roadway, construction of proposed roadway, and removal/relocation of existing utilities. The project site is identified as assessor's Parcel No. (1-11) Tax Map (48-4).

**EXISTING SITE CONDITIONS**

The entire site is undeveloped except for approximately 1,200 feet of existing roadway, drainage structures, and associated sanitary and water services. The site is moderately wooded with light understory. The landform in the general area is a rolling terrain with slopes varying from relatively flat to slopes of approximately 25 % along the ravine areas. Elevations within the project site generally range from elevation 3 to elevation 38. Drainage from the project is directed to tributary drainageways of College Creek.

**SOILS**

The predominant soil types which will be disturbed during the project construction are Craven-Uchee complex, Emporia complex, and Peawick silt loam, as depicted on soil mapping contained in the USDA - Soil Conservation Service, Soil Survey of James City and York Counties and the City of Williamsburg, Virginia.

Craven-Uchee complex consists of moderately well drained Craven soils and well-drained Uchee soils. Areas of this complex are on side slopes and narrow ridge tops. Typically, the surface layer of the Craven soils is dark grayish brown fine sandy loam

about 4 inches thick. The subsurface layer is pale olive fine sandy loam 5 inches thick. The subsoil extends to a depth of 42 inches. It is yellowish brown clay in the upper part and yellowish brown sandy clay loam mottled with gray in the middle and lower parts. The substratum is brownish yellow fine sandy loam mottled with gray in the upper part and gray loamy fine sand with yellow mottles in the lower part, and extends to a depth of at least 72 inches. Typically, the surface layer of the Uchee soils is dark grayish brown loamy fine sand about 5 inches thick. The subsurface layer is light yellowish brown and very pale brown loamy fine sand 19 inches thick. The subsoil extends to a depth of 56 inches. It is strong brown sandy clay loam and clay mottled with gray and red from 36 to 56 inches. The substratum from 56 to at least 65 inches is variegated red, brown, and gray stratified sandy loam and sandy clay loam. In the Craven soils, permeability is slow: and in the Uchee soils, it is moderate in the upper part of the subsoil and moderately slow in the lower part. The available water capacity is moderate for the Craven soils and low or moderate for the Uchee soils. Surface runoff is rapid. The erosion hazard is severe. The subsoil of both soils has moderate shrink-swell potential. During winter and early spring a seasonal high water table is at a depth of 2 to 3 feet in the Craven soil and 3 ½ feet to 5 feet in the Uchee soil. This soil is in capability subclass IVe. These soils are in hydrologic soil group C and A.

Emporia complex appears on side slopes along drainageways. Typically, the surface layer of this soil is dark grayish brown fine sandy loam about 4 inches thick. The subsoil extends to a depth of 45-50 inches and is yellowish brown loam with mostly strong brown mottles in the upper parts; yellowish brown, firm sandy clay loam with strong brown and gray mottles in the middle part; and mottled gray and brown, firm sandy clay loam in the lower part. The substratum is variegated gray, brown, and red, firm sandy clay loam to a depth of at least 75 inches. In this Emporia soil, permeability is moderate in the upper part of the subsoil and moderately slow to slow in the lower part. The available water capacity is moderate. Surface runoff is medium. The erosion hazard is moderate. The subsoil has moderate shrink-swell potential. A perched high water table is at a depth of 3 to 4 ½ feet in winter and spring. This soil is in capability subclass VIIe. The hydrologic soil group for this soil is C.

Peawick silt loam soil is deep, nearly level, and moderately well drained. It is on broad ridges of high stream terraces. Typically, the surface layer is dark grayish brown silt loam about 2 inches thick. The upper 14 inches of the subsoil is light yellowish brown silty clay loam and yellowish brown silty clay. The next 25 inches of the subsoil is mottled brown and gray silty clay. The lower part of the subsoil is mostly mottled, gray silty clay and clay to a depth of at least 99 inches. The permeability is very slow and the available water capacity is moderate. Surface runoff is slow and the erosion hazard is slight. The subsoil has a high shrink-swell potential. In winter and early spring, a perched high water table is at a depth of 1 ½ to 3 feet. These soils are in capability subclass IIw. The hydrologic soil group for this soil is D.

### **CRITICAL EROSION AREAS**

The soils identified on the site suggest a slight to severe erosion hazard. The potential for severe erosion exists along the slopes and within the ravine areas. No construction is anticipated within the more severe erosion hazard areas. All disturbed slopes will be stabilized by vegetative practices.

### **EROSION AND SEDIMENT CONTROL MEASURES**

Unless otherwise indicated. All vegetative and structural erosion and sediment control practices will be constructed and maintained according to minimum standards and specifications of the Virginia Erosion and Sediment Control Handbook, 1992, and in accordance with James City County Standards.

### **STRUCTURAL PRACTICE:**

The following practices are shown on the development plan sheets and detailed on erosion control details sheet.

1. **SILT FENCE (3.05)**

Silt fence will be installed where shown on the plan.

2. **STORM DRAIN INLET PROTECTION (3.07)**

Storm drain inlet protection will be installed for all drainage inlet structures where shown on the plan.

3. **OUTLET PROTECTION (3.18)**

Outlet protection shall be placed at all drainage outfalls.

4. **TREE PROTECTION (3.38)**

Tree protection fencing or other suitable devices shall be placed along the "clearing limits" to protect desirable trees from mechanical and other injury during land disturbing and construction activity.

### **VEGETATIVE PRACTICES:**

#### **1. TOPSOIL STOCKPILE**

Topsoil shall be stripped from areas to be graded and stockpiled for later use. The Owner shall approve stockpile locations.

#### **2. TEMPORARY SEEDING (3.31)**

All distributed areas on-site will be seeded with a fast-germinating, temporary vegetation immediately following grading or where exposed soil surfaces will not be brought to final grade for a period of time exceeding 15 days. Selection of the appropriate seed mixture as recommended by the Virginia Erosion and Sediment Control Handbook, 1992 will depend on the time of year it is to be applied.

### **MANAGEMENT STRATEGIES AND CONSTRUCTION SEQUENCE**

1. Establish tree protection/clearing limits flagging and erosion control devices.
2. Place all permanent erosion and sediment control devices, proceed with roadway clearing and grubbing operations. Proceed with demolition as shown on Demolition Plan.
3. If temporary stockpiles are used, the contractor shall install silt fences at the base to prevent sediment runoff. Stockpiles shall not be placed within any easement, or between the right-of-way and the building setback line.
4. Install sewer and water utilities, curb and gutter, sub-base materials and pavement surface course in the roadways.
5. Provide permanent seeding as required. Permanent seeding may take place at prior phases as deemed appropriate.


### **PERMANENT STABILIZATION**


All areas disturbed by grading will be stabilized with permanent seeding immediately following finish grading. Seeding will be done according to Std. and Spec. 3.32 of the Virginia erosion and Sediment Control Handbook, 1992. Permanently seeded areas shall be protected during establishment with straw mulch.

### MAINTENANCE

Maintenance of temporary erosion and sediment control devices is the responsibility of the developer. In general, all erosion and sediment control measures will be checked weekly and after each significant rainfall. Silt fencing shall be inspected immediately after each rainfall and at least daily during prolonged rainfall for undermining or repair. All seeded areas will be checked to insure a good stand of grass is maintained. Seeded areas deficient shall be reseeded as necessary.







## DEVELOPMENT MANAGEMENT

101-E MOUNTS BAY ROAD, P.O. BOX 8784, WILLIAMSBURG, VIRGINIA 23187-8784  
(757) 253-6671 Fax: (757) 259-4032 E-MAIL: devtman@james-city.va.us

ENVIRONMENTAL DIVISION  
(757) 253-6670  
environ@james-city.va.us

PLANNING  
(757) 253-6685  
planning@james-city.va.us

COUNTY ENGINEER  
(757) 253-6678

MOSQUITO CONTROL  
(757) 259-4116

March 3, 2006

Mr. Bruce Jackson  
2605 Jockey's Neck Trail  
Williamsburg, VA 23185 - 8057

Re: Lake Joachim Shoreline Work at 2605 Jockey's Neck Trail

Dear Mr. Jackson:

I appreciated the opportunity on January 23, 2006, to discuss the shoreline protection work you completed at your residence. As you are aware the regulatory status of Lake Joachim, changed in 2005. Because of a determination that perennial stream flow enters the lake, the Chesapeake Bay Preservation Ordinance requires Lake Joachim be designated as a protected body of water. As a protected body of water, there is a 100 ft Resource Protection Area Buffer that extends landward from the high water line around the lake, as well as a Best Management Practice (BMP) pond buffer extending 25 ft. We have reviewed the shoreline work and have determined that although prior approvals from the County were required an enforcement action at this time is not warranted given the minor nature of the impacts.


Please be advised that in the future, the Chesapeake Bay Preservation Ordinance requires that any proposed encroachment activity within that 100 ft buffer be reviewed and have written approval from the Environmental Division prior to the onset of work. Failure to obtain prior approval may constitute a violation of the County ordinance and can be subject to a civil penalty of up to \$5,000.00 per day.

Should you have any questions concerning any of this information please don't hesitate to contact me at 253-6675.

Sincerely,

Patrick T. Menichino  
James City County Environmental Division

CC: Darryl Cook  
Scott Thomas ✓  
The Vineyards HOA



## DEVELOPMENT MANAGEMENT

101-E MOUNTS BAY ROAD, P.O. BOX 8784, WILLIAMSBURG, VIRGINIA 23187-8784  
(757) 253-6671 Fax: (757) 253-6850 E-MAIL: [devtman@james-city.va.us](mailto:devtman@james-city.va.us)

CODE COMPLIANCE  
(757) 253-6626  
[codecomp@james-city.va.us](mailto:codecomp@james-city.va.us)

ENVIRONMENTAL DIVISION  
(757) 253-6670  
[environ@james-city.va.us](mailto:environ@james-city.va.us)

PLANNING  
(757) 253-6685  
[planning@james-city.va.us](mailto:planning@james-city.va.us)

COUNTY ENGINEER  
(757) 253-6678  
INTEGRATED PEST MANAGEMENT  
(757) 259-4116

January 16, 2001

Mr. David Coffield  
The Vineyards  
2400 Sarah Spence  
Williamsburg, Va. 23185

Re: The Vineyards  
Dam # 1 Joachin and Dam # 2 Ajacan Lakes  
Stormwater Management Facilities  
County Plan No. S-52-88; County BMP ID Codes (CC 013 and CC 005)

Dear Mr. Coffield:

At your request, the Environmental Division is forwarding information relative to a meeting held on October 18<sup>th</sup> for the above referenced facilities. In addition to specific comments as outlined below, the following additional information is also attached for your group's review and use:

- ☐ A 1 inch = 800 ft. scale map showing the general location of the development's two stormwater management facilities (lakes).
- ☐ Current Inspection Reports for the facilities as performed on November 28<sup>th</sup> 2000.
- ☐ Typical Maintenance Plans prepared for both facilities.
- ☐ General Landscaping Guidance (Tips).
- ☐ Two (2) Informative Brochures published by the Association of State Dam Safety Officials - *Dam Ownership: Responsibility and Liability* and *Dam Ownership: Procuring the Services of a Professional Engineer*.
- ☐ An informational brochure entitled *A Guide for Maintaining and Operating BMP's*. This publication is distributed through our office in response to a cooperative effort from the Hampton Roads Regional Stormwater Management Committee and HR STORM, a regional stormwater education effort coordinated by the Hampton Roads Planning District Commission.
- ☐ Information relative to the Virginia Department of Conservation and Recreation's Dam Safety Program, including summary information from their website and a copy of the Virginia Impounding Structure Regulations (1997).

Currently there are 3 sheets of plan and detail drawings related to design and construction of Dam #1 (Jochin) and Dam #2 (Ajacan) in our records file. These plans were prepared by AES Consulting Engineers (Project No. 6518) in July of 1986 and 1987. The plan for Dam #2 reflects an as-built status for the outlet structure dated June 1988. These drawings, as well as any hydrologic and hydraulic maps or computations, are available for sign out and reproduction by your group if desired.

General maintenance plans were prepared and provided for both facilities as a courtesy. The plans were prepared based on our general knowledge of maintenance required for these types of facilities and subsequent to our site specific inspections. It is provided for information and guidance purposes when no other specifically approved maintenance plans are available for use. The plans are not meant to replace or supersede any specific recommendations offered by a qualified professional.

The maintenance plans only address normal structural, stormwater runoff control and aesthetic activities related to safe function of the facility. Landscaping, cosmetic or ornamental features associated with the facility are usually left to the discretion of the Owner, or its designated representative, unless these features deter from the structural integrity or the performance of water quality/quantity controls as designed and constructed for the facility.

**Specific Comments about Dam #1 Jochin (Upper Lake - CC 013):**

Based on field observations, the facility appears to be in satisfactory condition for its age. Adequate maintenance mowing is being performed routinely on the top berm of the facility. However, the facility is in need of regular (routine) maintenance typical of most wet pond facilities. From our perspective, main concerns were the presence of trees on and along the downstream fill embankment; debris and tree growth in the vicinity of the riser structure; and minor joint leakage observed in the upper portion of the concrete riser structure.

The pond embankment is steep and high on the downstream face. Large trees to 6-inch diameter, smaller saplings and heavy ground cover and vegetation are present on most of the downstream embankment, especially lower portions of the embankment adjacent to normal pool of Dam #2 (Ajacan). Several of the larger trees are well-established and roots have penetrated into the embankment zone.

Usually trees, shrubs and woody vegetation are not permitted to grow on any part of pond embankments constructed using engineered (compacted) fills. Saturated roots mats combined with high wind can cause trees to overtop and accelerate soil erosion and embankment failure conditions. In addition, fluctuating water surface elevations in Dam #2 could potentially cause trees on the lower portion of the embankment to become exposed to saturated conditions, thus increasing the potential to die, overtop and create a structural concern for the Dam #1 embankment. Usually for this type of condition, we recommend that the subject trees be cut to or below ground level and be maintained in that fashion as to not disturb root systems that may already be extensive and efforts be made to replace the tree growth with an established low maintenance grass covering.

There was a considerable amount of trash, debris (leaves, dead tree branches, etc.) and trees and vegetation near and around the vicinity of the riser's DI-7 top grate. It is recommended to clean and remove all debris and trees from within 15 ft. of the riser to prevent unobstructed weir flow into the riser grate and to minimize root growth migration into the riser's joints.

Finally, there was a minor observation of seepage through the joints of the riser in its upper sections. This condition does not currently appear to be a major structural concern to the riser, however, an attempt to correct the condition should be performed concurrently with debris and tree removal operations around the riser. Although it does not appear the riser needs to be reset or replaced at the current time, interior joint sealing with grout should be performed to alleviate this condition. Continued migration of tree root systems through the riser could seriously displace the joints in the riser structure and cause structural instability.

**Specific Comments about Dam # 2 Ajacan (Lower Lake - CC 005):**

Adequate maintenance and mowing is being performed routinely on the top 1/3 portion of the facility along the paved curb and gutter roadway. However, the facility is in need of regular (routine) maintenance typical of most wet pond facilities and several non-routine maintenance action items were also noted. From our perspective, main concerns were the presence of trees on and along the bottom two-thirds portion of the downstream fill embankment; soft soils and minor seepage on the downstream west toe (emergency spillway side); soft soils and considerable seepage on the downstream east toe; degradation of the interior coating within the primary CMP outlet barrel; severe erosion and undercutting at the outlet barrel outfall; severe erosion and damage to the emergency spillway lining; and debris and tree growth in the vicinity of the riser structure.

Larger 2- to 6-inch trees, smaller saplings and heavy ground cover and vegetation are present on the entire bottom 2/3 portion of the downstream embankment. Several of the larger tree species are pine which pose a distinct threat to the structural integrity of the embankment. Usually trees, shrubs and woody vegetation are not permitted to grow on any part of pond embankments constructed using engineered (compacted) fills. Saturated roots mats combined with high wind can cause trees to overtop and accelerate soil erosion and embankment failure. Usually for this type of condition, we recommend that the subject trees be cut to or below ground level and be maintained in that fashion as to not disturb root systems that may already be extensive and efforts be made to replace the tree growth with an established low maintenance grass covering. For this case, we recommend that the maintenance zone, which is adequate on the upper 1/3 part of the downstream embankment be expanded in the same manner to include the lower 2/3 of the downstream embankment. This expansion can be performed all at once or phased over the next couple of maintenance (tree removal) cycles.

Soft soils and minor seepage was observed along the downstream left (west) embankment toe near the outlet barrel location. Although minor, this condition should be monitored and evaluated on a regular, continuing basis. A more discernible seepage area was observed along the downstream right (east) embankment toe approximately 125 ft. east of the outlet barrel. The seepage area was approximately 20 feet in length, had an approximate 12 inch depth and flow was considerable (estimated at > 1 gpm). Discoloration and an oily film was observed on the surface of the discharge from the seep area. This area should be inspected by a qualified professional engineer and its effect/impact to the structural integrity of embankment properly evaluated. In addition, the seepage area should be monitored in the future on a regular, continuing basis.

At the downstream end of the principal spillway outlet barrel (36-inch CMP), the end section was undercut by erosion into the dam embankment approximately 3 feet. Continued erosion under the barrel threatens the integrity of the outlet barrel and dam embankment toe. Remediation should include removal of the end section, proper placement of compacted soil material, resetting the flared end section and placement of armor protection over the soil to prevent reoccurrence.



The outlet protection pad at the barrel outfall is missing and needs replaced and a large tree (and rootmat) which has fallen at the outlet protection location needs removed.

Based on observation, the bituminous coating within the lower end of the 36-inch outfall barrel appeared worn and flaking, especially in the bottom portion of the pipe up to about ½ pipe depth. Although the inner metal wall of the pipe did not appear corroded, over time a lack of and continued loss of the inner pipe wall coating will tend to lead to premature corrosion and possible failure of the outlet barrel. It is highly suggested that a suitable lining be re-established in the pipe interior where loss has occurred. There are several after market type in-situ lining materials that can be applied to protect the pipe inner wall from further degradation.

There was a considerable amount of trash and wood debris and trees and vegetation near and around the vicinity of the riser's DI-7 top grate and its rectangular weir slot. Clean and removal of all debris and trees from within 15 ft. of the riser is recommended to prevent unobstructed weir flow to the riser grate and to minimize root growth migration into the riser joints. Also, exposed rebar was present on all three - 18 inch diameter emergency spillway overflow pipes on the upstream side of the embankment.

Of primary concern to the integrity of the facility is a severe erosion and undercutting condition observed along the outlet channel portion of the emergency spillway. All erosion protection rock (riprap) which was placed within the channel has displaced and the underlying geotextile is fully exposed and damaged. A 7' wide x 7' long x 4' deep scour hole has formed at the bottom of the spillway. The emergency spillway has fully failed, offers no type of erosion protection for larger storm events and is in need of immediate attention to restore it back to its intended design function. Continued erosion and undercutting along the emergency spillway outlet channel poses a severe threat to the integrity of the downstream embankment.

#### Interior Storm Drainage System:

Spot checks were performed at several of the inlets/storm drain systems tributary to Dam # 2. In general, these systems are small cross-culvert and collection subsystems which are mainly located at road profile low points. These systems collect "through" (on and offsite) drainage from open channels and roadside drainage via paved roadway and curb and gutter flow. Based on our physical inspection of approximately 6 inlets within 2 of the storm drainage subsystems on the eastern side of Jockey's Neck Trail, the systems appear to be adequate for their intended function and appear to be routinely cleaned and maintained, as no accumulations of leaves, debris, etc. was observed beyond that to be expected during the fall/early seasons.

#### Other:

Some concern was presented about whether the lower lake, Dam # 2 Ajacan (CC 005) fell under the criteria of a permitted dam facility per the Virginia Dam Safety regulations. These regulations exclude a dam if the downstream embankment is less than 25 feet (as measured from the streambed at the downstream toe to top of the impounding structure) and creates a maximum impoundment greater than 50 acre-feet. There are also provisions for exclusion of dams constructed, maintained or operated primarily for agricultural purposes which are less than 25 feet in height or which create a maximum impoundment smaller than 100 acre-feet.

Based on our cursory review of file information, design volume to El. 25.0 is approximately 124.33 acre-feet and original design top of dam is at El. 28.5; therefore, there appears to be volume well in excess of either 50 or 100 acre-feet. Original design dam height was approximately 24.5 feet (El. 28.5 - El. 4.00 = 24.5 feet). Per as-built information dated June 27<sup>th</sup> 1988, the actual downstream invert of the outlet barrel was defined as El. 5.22 rather than El. 4.00 per design, thus resulting in a dam height of 23.28 feet (El. 28.5 - 5.22 = 23.28 feet). In August of 1989, computations as performed to size an emergency spillway pipe system across the embankment/roadway reflected a road centerline design elevation at El. 30.0, which would result in a dam height of 24.78 feet (El. 30.0 - El. 5.22 = 24.78 feet). Although it appears the original dam design and modifications would not require the facility to fall under state permitting criteria because of dam height, our records do not reflect any as-built information for the top of the facility; thus it is unclear if 25 feet in vertical distance is present.


It is our recommendation that dam height be confirmed via field survey based methods, and since land-use alterations may have changed original classifications assigned to the dam, determination of permits and classification under the Dam Safety Act requirements, if necessary, be coordinated with the following office:

Department of Conservation and Recreation  
Division of Dam Safety  
203 Governor Street, Suite 402  
Richmond, Va. 23219  
Att: Mr. Jon Phillippe  
804-786-1369

I have attached some general information from the Virginia dam safety program website at [www.dcr.state.va.us/damsafty](http://www.dcr.state.va.us/damsafty) and my most current copy of the Virginia Impounding Structure regulations for your review.

Hopefully, this material is helpful to your group to understand maintenance associated with both facilities. Please review the attached information and contact us at 757-253-6639 or 757-253-6673, if you have any further questions or comments.


Sincerely,

  
Scott J. Thomas, P.E.  
Civil Engineer  
Environmental Division

SJT/sjt  
Enclosures

cc: Robert Emmett

Shared\SWMPProg\Education\Subdivisions\Vineyards.lett1



# James City County Environmental Division

## Stormwater Management / BMP Inspection Report

### Detention and Retention Pond Facilities

S-52-88  
GPIN 4840100011

Database Inventory No. (if known): CC013

Name of Facility: VINEYARDS @ JOCKEYS NECK

SEC 1 & 2 DAM #1 JOACHIN LAKE

BMP No.: 1 of 2

Date: 11/28/00

Location: Behind 2609 JOCKEYS NECK TRAIL (LOT 70) GPIN

Name of Owner: \_\_\_\_\_

Inspector: SJ Thomas

Type of Facility: Wet Pond (Dam)

Weather Conditions: Sunny, Mild, 50's

If an inspection item is not applicable, mark NA, otherwise mark the appropriate column.

(NOTE: UPPER LAKE)  
EMBANK 1/5

O.K. - The item checked is in adequate condition and the maintenance program is currently satisfactory.

Routine - The item checked requires attention, but does not present an immediate threat to the function of the BMP.

Urgent - The item checked requires immediate attention to keep the BMP operational and prevent damage to the facility.

Provide an explanation and details in the comment column, if routine or urgent are marked.

Facility Item	O.K.	Routine	Urgent	Comments
Embankments and Side Slopes: <u>STEEP D/S 2H:1V &amp; HIGH; U/S 3H:1V LOW</u>				
Grass Height	X			Good Cover 100% EMBANK.
Vegetated Condition		X	X	SMALL SAPLINGS TO 6" DIA PINES, WILLOWS & TREES
Weed Growth		X	X	Brush & Small Trees
Erosion	X			Minor Erosion AT Toe. DAM #2 HWL. DUE TO
Trash & Debris	X			None.
Seepage				MINOR SPOT D/S LEFT (WEST) ABUTMENT.
Fencing or Benches	X			None.
Constructed Wetlands (Interior Landscaped & Planted) Areas: <u>NATURAL, WET POOL</u>				
Vegetated Conditions				N/A
Trash & Debris				N/A
Floatables				N/A
Erosion				N/A
Sediment				N/A
Dead Plant				N/A
Aesthetics				N/A
Other				N/A
				N/A

Facility Item	O.K.	Routine	Urgent	Comments
<b>Water Pools</b> <input checked="" type="checkbox"/> Permanent Pool (Retention Basin) <input type="checkbox"/> Shallow Marsh (Detention Basin)				
Shoreline Erosion	X			Acceptable. More prevalent at Toe-Lawn Areas.
Algae	X			None observed.
Trash & Debris	X			
Sediment	X			UNKNOWN. POOL NOT ACCESSIBLE.
Aesthetics	X			GOOD NATURAL LOOK.
Other				
<b>Inflow Structures (Describe Locations):</b> VARIOUS SHEET, OPEN CHANNEL & STORM DRAIN INFLOWS.				
Condition of Structure	X			
Erosion	X			
Trash and Debris	<del>X</del>	X		Routine Channel & Inlet/storm DRAIN CLEANING RECOMMENDED. SLIGHT BUILDUP WITH LEAVES BUT FREE-FLOWING
Sediment	X			
Aesthetics	X			
Other	X			CHECKED 4 INLETS TRIB TO DAM (EAST)
<b>Principal Flow Control Structure - Intake, Riser, etc. (Describe Location):</b> SOUTH END, MID EMBANK.				
Condition of Structure	X			Riser RCP 4' Ø w/STEPS, MINOR JOINT LEAKAGE
Corrosion	X			
Trash and Debris		X	X	Clear & Remove Debris, Leave, Trees & Sed 15' from Riser. (SED 12" DEEP AT RISER)
Sediment	X			
Aesthetics		X	X	cleaning Top UNIT. (Flat)
Other				Riser 3x3 DI-7 Top, >25' DEEP
<b>Principal Outlet Structure - Barrel, Conduit, etc. :</b> COULD NOT BE IDENTIFIED U/S OR O/S. 36" RCP BY PLAN				
Condition of Structure	X			Appears functional, about 1" flow over riser crest is outletting o/s thru barrel in riser. No excessive ponding within riser.
Settlement				
Trash & Debris				
Sediment				
Erosion				
Other				
<b>Emergency Spillway (Overflow):</b> EAST SIDE EMBANKMENT THRU ADJACENT LOT AREAS.				
Vegetation	X			
Lining	X			GRASS
Erosion		X	X	Erosion @ O/S Toe RT (EAST) EMB.
Trash & Debris	X			
Other				Functional during flood (Floyd)
Based on historical reports, ES flow occurred at east side embankment Depth < 6" thru LOT AREAS during Hurricane Floyd Sept 1999				

Facility Item	O.K.	Routine	Urgent	Comments
<b>Nuisance Type Conditions:</b>				
Mosquito Breeding	X			
Animal Burrows	X			None observed. Rabbit + Grouse on O/S EMB.
Graffiti	X			
Other				
<b>Surrounding Perimeter Conditions:</b>				
Land Uses	X			Mixed Wooded + Lot, Alternating.
Vegetation	X			Good Natural Butters.
Trash & Debris	X			
Aesthetics	X			Natural setting.
Access /Maintenance Roads or Paths	X			Good Access FROM West. CLEARED 15' PATH.
Other	X			VINEYARD AREA U/S DRAINS TO POND.
<p><b>Remarks:</b> ▷ LARGE Trees + Saplings WERE Removed D/S EMB. HIGH HAZARD DUE TO D/S SLOPE STEEPNESS.</p> <p>▷ Minor Seepage Spot Left (West) Abutment toe. Continue to monitor.</p> <p>▷ Riser 3x3 DI-7 top on 48" RCP Riser. Outlet barrel SIZE COULD NOT BE IDENTIFIED U/S (DEEP IN Riser) AND O/S (SUBMERGED)</p> <p>▷ Clean + Remove all leaves, debris AND trees (willows) AND brush 15' from riser. obstructing weir flow into top grate.</p> <p>▷ Minor Leakage upper section joints of riser. needs reset or sealed with grout. Does not appear to be a major structural concern, but releases enough flow to drain down pool. At time of inspection very little weir flow over riser, but large amount of flow within riser.</p> <p>▷ Lots - Roadways Curb + gutter to Inlets/storm DRAINS.</p>				
Overall Environmental Division Internal Rating: <u>2</u> (O/S EMBANKMENT GROWTH.)				
Signature: <u>Swift Thomas P.E.</u>		Date: <u>11/28/00 2:40 pm</u>		
Title: <u>Civil Engineer Environmental Div.</u>				

SWMPProg\BMP\ColnspProg\DetRet.wpd

**DAM SAFETY PROGRAM**  
**DEPARTMENT OF CONSERVATION & RECREATION**  
 Division of Dam Safety  
 203 Governor Street, Suite 402  
 Richmond, Virginia 23219-2094

**OWNER'S ANNUAL INSPECTION FORM**

*VINEYARDS @ JOCKEYS NECK SEC 1 & 2*

Name of Dam DAM #1 JOACHIN LAKE Inventory Number JCC CC 013  
 Name of Reservoir UPPER LAKE County/City JCC  
 Owner's Name \_\_\_\_\_ Hazard Class I, II, III or IV N/A  
 Address \_\_\_\_\_ Inspected by SJ THOMAS SHT.  
 Date 11/28/00  
 Telephone ( ) \_\_\_\_\_

DIRECTIONS: MARK "X" in YES, NO or N/A COLUMN

ITEM	YES	NO	N/A	REMARKS
<b>1. GENERAL CONDITIONS</b>				
A. Alterations to dam?		X		
B. Development in downstream flood plain?		X		LAKE #2 DIRECTLY D/S.
C. Grass cover adequate? (embankment & spillway)	X			
D. Settlements, misalignment, or cracks?		X		
E. Recent high water marks?		X		Elevation:
<b>2. UPSTREAM SLOPE</b>				
A. Erosion?		X		
B. Trees?	X			SMALL TREES, WEEDS? BRUSH
C. Rodent holes?		X		
D. Cracks, settlement, or bulges?		X		
E. Adequate and sound riprap?			X	
<b>3. INTAKE STRUCTURE</b> <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Metal				Water Surface Elevation: <u>UNKNOWN @ RISER</u> CREST: 1" DEPTH
A. Spalling, cracking, scaling?		X		EL. 40.1
B. Exposed reinforcement?		X		
C. Corrosion present?		X		
D. Coating adequate?	X			
E. Leakage?	X			MINOR Upper Joint LEAKAGE
F. Trash rack adequate?		X		NONE. DI-7 TOP GRATE
G. Obstacles to inlet?	X			Debris, LEAVES? TREES WITHIN 15'
H. Drawdown operative? <input type="checkbox"/> Closed <input type="checkbox"/> Open		X		NONE observed.
<b>4. ABUTMENT CONTACTS</b>				
A. Erosion, cracks or slides?		X		
B. Seepage?	X			Estimated GPM: <5, MINOR D/S LEFT WEST EMB.
<b>5. EMERGENCY SPILLWAY</b>				EAST SIDE THRU ADJ. LOTS
A. Obstructions?	X			DOWNSTREAM CHANNEL
B. Erosion?	X			D/S TOE @ RT EAST EMB
C. Rodent holes?		X		
<b>6. DOWNSTREAM SLOPE</b>				
A. Erosion?	X			MINOR DUE TO D/S LAKE 2 LEVELS
B. Trees?	X			SMALL SAPLINGS? 6" DIA. PINE
C. Rodent holes?				



## OWNER'S ANNUAL INSPECTION FORM

Inventory Number JCC CC013

ITEM	YES	NO	N/A	REMARKS
D. Cracks, settlements or bulges?		X		
E. Drains or wells flowing?		X		Estimated GPM:
F. Seepage or boils?		X		Estimated GPM:
7. CONDUIT AND OUTLET <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Metal				Tail water elevation and flow: LAKE #2 NP
A. Spalling, cracking, scaling?		X		
B. Exposed reinforcement?		X		
C. Joints displaced or offset?		X		NOTE: COULD NOT OBSERVE
D. Joint material lost?		X		36" Ø OUTLET
E. Leakage?		X		BARREL.
F. Earth erosion?		X		
G. Conduit misaligned?		X		
H. Outlet channel obstructed?	X			BELOW N.P. LAKE 2
8. STILLING BASIN				COULD NOT OBSERVE
A. Spalling, cracking, scaling?		X		
B. Exposed reinforcement?		X		
C. Joints displaced or offset?		X		
D. Joint material lost?		X		
E. Joints leak?		X		
F. Rock adequate?		X		
G. Dissipators deteriorating?		X		
H. Dissipators clean of debris?		X		
9. CONCRETE SPILLWAY			X	NOT APPLICABLE
A. Spalling, cracking, scaling?				
B. Exposed reinforcement?				
C. Joints displaced or offset?				
D. Joint material lost?				
E. Leakage?				
F. Dissipators deteriorating?				
G. Dissipators clean of debris?				
H. Earth erosion?				
I. Outlet channel eroding?				
10. GATES			X	NONE
A. Floodgates broken, bent?				
B. Floodgates eroded or rusted?				
C. Floodgates operational?				
11. RESERVOIR				
A. Development?	X			SF LARGE LOTS (WOOD & GRASS)
B. Slides or erosion on banks?		X		
C. Reservoir managed?	X			SF UNITS
12. INSTRUMENTS			X	NONE
A. Is structure instrumented?				
B. Monitoring performed?				
13. SHOULD DAM BE INSPECTED BY ENGINEER?				
14. REEVALUATE HAZARD CLASSIFICATION				
15. IS EMERGENCY ACTION PLAN CURRENT?				
REMARKS: FUNCTIONAL DURING HUR FLOYD. LARGE TRIPS & SAPLINGS D/S EMB				
NEED REMOVED. MINOR SEEPAGE SPOT TO BE MONITORED. CLEAN & REMOVE				
TREES 15' FROM RISER INLET. REPAIR MINOR LEAKAGE UPPER JOINTS RISER.				

Date Record Created:

Created By:

WS\_BMPNO:

CC013

Print Record

WATERSHED

CC

BMP ID NO

013

PLAN NO

S-84-89

TAX PARCEL

PIN NO

4840100011

CONSTRUCTION DATE

PROJECT NAME

Vineyards at Jockey's Neck -Jochain

FACILITY LOCATION

CITY-STATE

Williamsburg, VA

CURRENT OWNER

OWNER ADDRESS

OWNER ADDRESS 2

CITY-STATE-ZIP CODE

OWNER PHONE

MAINT AGREEMENT

No

EMERG ACTION PLAN

No

PRINTED ON

Wednesday, March 10, 201

2:32:58 PM

MAINTENANCE PLAN

No

SITE AREA acre

661

LAND USE

SF Residential

old BMP TYP

Wet Pond

JCC BMP CODE

A2 Wet Pond

POINT VALUE

SVC DRAIN AREA acres

108.8

SERVICE AREA DESCRI

SF Lots, Roadways & Offsite Vineyards

IMPERV AREA acres

22.00

RECV STREAM

Pates Creek

EXT DET-WQ-CTRL

No

WTR QUAL VOL acre-ft

CHAN PROT CTRL

No

CHAN PROT VOL acre-ft

SW/FLOOD CONTROL

Yes

GEOTECH REPORT

No

CTRL STRUC DESC

RCP Riser

CTRL STRUC SIZE inches

60

OTLT BARRL DESC

RCP

OTLT BARRL SIZE Inch

36

EMERG SPILLWAY

Yes

DESIGN HW ELEV

40.0

PERM POOL ELEV

37.0

2-YR OUTFLOW cfs

40.03

10-YR OUTFLOW cfs

69.90

REC DRAWING

No

CONSTR CERTIF

No

LAST INSP DATE

11/28/2000

Inspected by:

INTERNAL RATING

2


MISC/COMMENTS

This is Upper Lake - Jochain -connects to downstream Dam # 2 Ajachan CC 005.

Get Last BMP No

Return to Menu

Additional Comments:



CC013\_VINEYARDS\_AT\_JOCKEYS\_NECK\_DAM\_1 - 052

**ENVIRONMENTAL DIVISION REVIEW COMMENTS**

**The Vineyards att Jockey's Neck, Phase 3**

**S-018-02**

February 26, 2002

MDW/DEL

**General Comments**

1. A Land Disturbing Permit and Siltation Agreement are already in place for this project.
2. The Subdivision Agreement and surety in place for Phase 3 will need to be revised as a new plat will be recorded for the subdivision.
3. Provide final contours on the plan in the area of the abandoned road and right-of-way.
4. Provide additional silt fence along the western side of the proposed demolition for the road.



7/31/06

Scott,

Thanks. It looks  
like the upper  
dam was not  
built to the  
drawing.

Bill Robert  
253-8504



**DAN REEVES**

V.P. - Operations

Plant  
240 McGhee Road  
P.O. Box 4386  
Winchester, VA 22604

Office: 877-877-5727  
540-722-4694

Fax: 540-722-2219  
Email: [d.reeves@plastic-solution.com](mailto:d.reeves@plastic-solution.com)  
[www.plastic-solution.com](http://www.plastic-solution.com)



**“Permanent Solutions  
to all your  
water screening needs”**




**Plastic Solutions, Inc.** is pleased to introduce its line of *structural plastic* trash racks and debris cages for storm water management basins and pond structures. Plastic Solutions offers a full line of standard sizes and can also customize to fit your specific requirements. Available in concrete grey and black.



**5000 lb. truck** is supported by four 48" Pyramid structures.

*Structural plastic* has a cellular core surrounded by integral skins forming a totally integrated structure. Structural molded parts made from H.D.P.E. and fiberglass have a high strength-to-weight ratio and have 3 to 4 times greater rigidity than solid parts of the same material of equal weight.

Trash racks are available in numerous sizes and shapes to accommodate nearly every type of application.



**Trailside Residential Subdivision**





**Dulles Toll Road**

# 

(STANDARD SIZES)

Dimensions in Inches to the Nearest 1/4"



### Pyramid Racks for Concrete Pipe

--- Pipe ---

Part No.	I.D.	O.D.	A	B	C
PYD-24	24	30	30	7 1/2	11 3/4
PYD-36	36	44	44	13	19 1/4
PYD-48	48	58	58	13	21 1/4
PYD-60	60	72	71	17 3/4	28
PYD-72	72	86	84	23 1/2	31 3/4
PYD-84	84	100	94 1/2	25 1/2	39 1/2
PYD-96	96	114	114	22 3/4	39 1/2

### Pyramid Racks for Plastic and Metal Pipe

(Includes Fastening Kit)

----- Pipe -----

Part No.	Corrugated	Plastic	A	B	C
PYDP-24	12,15,18	12,15,18	30	7 1/2	11 3/4
PYDP-36	21,24,27,30	24,30	44	13	19 1/4
PYDP-48	33,36,42	36,42	58	13	21 1/4
PYDP-60	48,54	48	71	17 3/4	28
PYDP-72	60,66	60	84	23 1/2	31 3/4
PYDP-84	72,78		94 1/2	25 1/2	39 1/2
PYDP-96	84,90,96		114	22 3/4	39 1/2



CAD Drawings Available from Our Website [www.plastic-solution.com](http://www.plastic-solution.com)


P.O. Box 4386 • Winchester, VA 22604 • 540-722-4694 • 877-877-5727 • Fax: 540-722-2219



## FLAT ROOF RECTANGULAR RACKS/WEIRS

(Standard Sizes)

Dimensions in Inches to the Nearest 1/4"



### STANDARD WIDTHS

A	11 3/8	16 3/4	22 1/8	27 1/2	32 7/8	38 1/4	43 5/8	49	54 3/8	59 3/4	65 1/8	71 1/8	76 1/2	81 7/8	87 1/4
Width Code	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16

### STANDARD LENGTHS

B	11 3/8	16 3/4	22 1/8	27 1/2	32 7/8	38 1/4	43 5/8	49	54 3/8	59 3/4	65 1/8	70 1/2	75 7/8	81 7/8	87 1/4
Length Code	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16

### STANDARD HEIGHT

C	7 1/2	12 7/8
Height Code	01	02

PART CODE = FR

Width Code Length Code Height Code


(example: FR080802)

\*\*\*\*\* CUSTOM SIZES AVAILABLE UPON REQUEST \*\*\*\*\*

## PEAK ROOF STRUCTURE

(Standard Sizes)

Dimensions in Inches to the Nearest 1/4"



### STANDARD WIDTHS AND HEIGHTS

A	49 3/4	59 3/4	69 1/2	79 1/2	89 1/2	99 1/2	109 1/4	120 1/2
Width Code	10	12	14	16	18	20	22	24
C	18	20	22	24	26	28	30	32

### STANDARD LENGTHS

B	49	54 1/2	59 3/4	65 1/4	70 1/2	76	82	87 1/4	92 3/4	98	103 1/2	108 3/4
Length Code	09	10	11	12	13	14	15	16	17	18	19	20







PART CODE = PR

Width Code Length Code Height Code

(example: PR121201)

\*\*\*\*\* CUSTOM SIZES AVAILABLE UPON REQUEST \*\*\*\*\*

CAD drawings can be downloaded from our website.



Pyramid racks are available with an anti-vortex device, but through empirical testing, the configuration of the grid pattern mitigates the need for a plated anti-vortex device.



*For more information, please contact  
Plastic Solutions, Inc. at:*


*P.O. Box 4386 • Winchester, VA 22604*

*540-722-4694 • 877-877-5727 • Fax: 540-722-2219*


*Visit our website at <http://www.plastic-solution.com>*




Racks can be mounted  
on concrete structures,  
plastic and metal pipe.



Flat Roof  
on Concrete Structure



Pyramid on  
Metal Pipe




Pyramid on  
Concrete Structure



Pyramid on  
Corrugated Pipe

Racks are designed to withstand the conditions of pond structures - rough handling, high/low temperatures and long term weather exposure. **Structural plastic** has replaced wood, concrete, solid plastics and metals in a variety of applications. With **structural plastic**, you can take advantage of the many benefits such as:



Belmont Green Recreation Area  
(Design Flexibility)




Hunting Ridge Townhouses

- Lighter Weight
- Elimination of Corrosion
- Design Flexibility
- Greater Part Stiffness and Stability
- Chemical Resistance
- Installation Savings



Installing Pyramid at  
Trex Manufacturing Facility  
(Installation Savings)



Frederick County Landfill

**Structural plastic** racks are a great alternative to painted and galvanized steel racks for use in storm water management ponds and general water screening. **Structural plastic** provides a structurally sound product with a long lasting quality appearance.

### **SWM/BMP Maintenance Plan for Dam # 1 Joachin Lake (CC 013)**

***( Note: This is a typical Maintenance Plan for your Retention Pond facility. For general use by HOA's, or other designated parties which are responsible for operation, maintenance and inspection of the facility when no other specifically approved plans are available. This is provided as a courtesy by the Environmental Division of James City County for informational purposes only. This plan addresses normal structural and stormwater runoff control aspects of the facility. It does not address landscaping, cosmetic, or ornamental features associated with the facility nor does it replace any specific recommendations offered by a registered professional. )***

#### **Maintenance Plan (Retention Pond BMP's)**

A maintenance program is required to ensure the Stormwater Management (SWM) / Best Management Practice (BMP) pond facility functions as designed and to provide for reasonable aesthetic conditions. Proper maintenance is encouraged to prevent the introduction of debris and sediment into pretreatment areas, the SWM/BMP itself, its principal inflow and outflow control structures and downstream waterways. Following facility installation, acceptance and establishment of vegetation in disturbed areas, inspections for sediment buildups should be performed at least quarterly. It is anticipated that under normal conditions, sediment removal will be required once every 5 to 10 years. If other construction or related land-disturbing activities are performed upland of the BMP, adequate protection measures should be implemented and inspection frequencies increased to at least once weekly.

The designated party will inspect the SWM/BMP structure after each significant rainfall event or the following working day if a weekend or holiday occurs. A significant rainfall for this structure is defined as one (1) inch or more of gauged rainfall within a 24 hour period. Once per year (more or less) a representative of the County may jointly inspect the structure. Appropriate action will be taken to ensure appropriate maintenance. Keys to locked access points or structures shall be made available to the County upon request and adequate notice should be given to nearby residences of inspection activities that may take place.

**Facility Description:** Dam # 1 Joachin Lake is located in the north central portion of Section 1 and 2 of the Vineyards and serves a drainage area of 108 acres associated with development of the subdivision and offsite area. The facility is wet-type retention lake facility. A wet-type retention pond has a permanent impoundment which enhances water quality and is normally "wet" even during non-rainfall periods. The facility contains a 60-inch vertical concrete pipe riser, a DI-7 inlet top grate unit, a 36-inch concrete outlet pipe barrel and a grass-lined shallow emergency spillway located to the east of the embankment. There is an approximate 7 ft. wide by 18 inch high opening in the riser pipe to provide for draw down and to offer control for larger storm events. During the 100-year storm, the maximum water level should rise to just above the riser structure which is 3.5 feet from top of dam at design El. 43.5. Higher water levels should draw down in about 24 to 36 hours.


#### **Inspection and Maintenance of the Facility Should Consist of the Following Additional Measures:**

1. Inspect for sediment buildup by visual observation and a physical determination of sediment depth within pond's storage area. If sediment reaches a substantial depth above the bottom of pond, removal is required. At the same time, or at least once per year, clean pretreatment devices, the riser bottom and outlet pipes of accumulated sediments. Dispose of sediments removed from the facility at an acceptable disposal area. (Note: Cleanout Elevation is approximately 10 percent of design Water Quality Volume.)

2. Perform maintenance mowing of pond grasses at least twice each year. Grasses such as tall fescue should be mowed in early summer after emergence of the heads on cool season grasses and in late fall to prevent seeds of annual weeds from maturing. Mowing of legumes can be less frequent. Trees, shrubs and woody vegetation are not be permitted to grow on any part of pond embankment that was constructed using engineered (compacted) fills.
3. Perform soil sampling on stabilized pond soil areas at least once every 4 years. Soil sampling and testing should be performed a qualified independent soil testing laboratory such as VPI&SU. Apply additional lime and fertilizer in accordance with test recommendations.
4. In stabilized pond areas, if vegetation covers less than 40 % of soil surfaces, lime, fertilize and seed in accordance with recommendations for new seedlings. If vegetation covers more than 40 % but less than 70 % of soil surfaces, lime, fertilize and over seed in accordance with current seeding recommendations of the Virginia Erosion and Sediment Control Handbook (VESCH).
5. Perform quarterly inspections of the riser section and crest spillway for the observance of collected trash and debris. Immediately remove any trash or debris that prevents the movement of water. Remove any trash and litter downstream and at storm drain or channel inflow locations to maintain the integrity of the structure and provide an attractive appearance.
6. Perform yearly structural inspections of the facility for damage. Structural inspection shall be performed on the concrete riser, overflow grate, rectangular weirs, outlet barrel and pond embankment. Exposed metal surfaces shall be painted to minimize rust damage or replaced if rust damage is irreversible. If damage is evident, further investigation by a registered professional engineer may be required to assess the integrity of the structure.
7. Perform quarterly inspections of the graded side slopes of the facility for signs of animal/rodent borrows or slope erosion. Immediately perform necessary repairs, refilling or reseedling.
8. Perform yearly observations of perimeter areas surrounding the facility to ensure changes in land use, topography or access have not occurred and do not affect the operation, maintenance, access or safety features provided for the facility. Appropriate action is required to ensure adequacy and to provide a clear, safe passage for maintenance vehicles to the engineered embankment and principal flow control structures.
9. Inspect and exercise pond drain valves, if provided, on a regular basis.
10. Record Keeping. Keep reasonable, accurate written records of inspections and maintenance activities performed for the BMP structure at all times. Records shall document routine maintenance and/or repairs performed. Copies shall be provided to the County upon request.
11. The facility shall not accept additional drainage or be modified in any way without prior consent or approval by the Environmental Division of James City County.

**( End )**

TRANSMITTAL



**DATE:** February 11, 2002

**TO:** [REDACTED]

Fire  
Health  
VDOT  
JCSA  
County Engineer  
Real Estate

**FROM:** Dave Anderson, Planner

**SUBJECT:** Case No. S-018-02 The Vineyards at Jockey's Neck, Phase III

**ITEMS ATTACHED:** Subdivision plan  
Supporting Engineering Docs

**INSTRUCTIONS:** Please review and comment

**RETURN REQUESTED BY:** February 25, 2002

**AGENCY COMMENTS:**

Is this development served by Newport News Water Works? \_\_\_\_\_ (JCSA please check if yes)

If checked, PLANNER please fax copy of preliminary approval letter with Fire Department comments, and the JCSA completed water data sheet to Newport News Water Works - Chief Engineer as soon as all three are available  
(Fax # 247-2334)



# MEMORANDUM

**Date:** January 16, 2001

**To:** Jon Phillippe, Department of Conservation & Recreation  
Division of Dam Safety *SAT*

**From:** Scott J. Thomas

**Subject:** The Vineyards at Jockeys Neck Subdivision  
James City County, Virginia

---

For your information, I have attached a full copy of report forwarded to a representative of the homeowner's association for the above referenced subdivision. There are two lakes associated with the development and there has been some question as to whether the lower lake, Dam # 2 Ajacan Lake should fall under the state permit requirements.

I am forwarding information that I have compiled to this point in this packet. It includes a cover letter outlining our inspection of the two facilities, a location map and inspection reports (both in County and state inspection form formats). If you need any other information such as original design computations, drainage maps, etc., please contact me at 757-253-6639 to discuss.

I don't think there is any immediate action required on your part; however, I am forwarding a copy to you as a courtesy since I referenced your office on page 5 of the report and forwarded some general information from the Division of Dam Safety.

MAIL TO:  
Department of  
Conservation & Recreation  
Division of Dam Safety  
203 Governors Street  
Suite 402  
Richmond, VA. 23219  
ATTN: MR. Jon Phillippe

